



ERNEST ORLANDO LAWRENCE
BERKELEY NATIONAL LABORATORY



Integrated Functional Appraisal

Environmental Energy Technologies Division

FY 2004

IFA Team Members

*Larry McLouth, IFA Team Leader & Industrial Hygiene and
Laboratory Safety – EH&S*

Kim Abbott, DOE Berkeley Site Office

Cathy Wentworth, RN - Health Services

Matt Kotowski, Safety Engineer – EH&S

Guy Kelley, EETD Safety Coordinator

August 24, 2004

Executive Summary

The Environment, Health and Safety Division (EH&S) conducted an Integrated Functional Appraisal (IFA) of the Environmental Energy Technologies Division (EETD) during April and May 2004. The IFA consisted of initial scope discussions, record review, and inspection of the space to identify uncontrolled hazards and to recommend control measures. The scope of the IFA focused on areas where activities requiring formal authorizations took place. The inspection team consisted of specialists from EH&S, the EETD Safety Coordinator, and a U.S. Department of Energy Berkeley Site Office (DOE/BSO) observer.

A total of 115 observations were noted during the field inspections. The majority of these pertained to electrical safety, chemical safety, and machine guarding. These are summarized below. A detailed list of the IFA findings and recommended corrective actions is presented in Appendix 1.

Electrical Safety: Electrical safety issues included inappropriate use of extension cords, damaged electrical cords, improper cable trays bonding/grounding, and blocked electrical disconnects and panels. Several eyewash/safety showers or drench hoses are located near energized circuits. This was noted during the previous (FY 2001) IFA. A Laboratory-wide effort is underway to correct deficiencies of this nature.

Chemical Safety: In general, chemical safety was satisfactory, but some issues were noted, such as improper secondary containment, clutter in fume hoods, and labeling deficiencies.

Machine guarding: Several pieces of equipment (band saws, mills, belt sanders and drill presses) had exposed moving parts.

It should be noted that EETD had made a number of improvements since the last IFA was conducted in 2001. In particular, seismic safety, housekeeping, and ergonomics had greatly improved.

Safety within EETD has exceptional management support. The Division has a proactive safety program that is both innovative and effective. The commitment of EETD is proven by the condition of the spaces evaluated and the safety-conscious attitude demonstrated by the individuals (supervisors and staff members) encountered during the field visits.

Table of Contents

| Section | Page |
|---|-------------|
| 1 Introduction..... | 1 |
| 2 Appraisal Process | 1 |
| 2.1 Determination of Scope, Preparation for Site Visits | 1 |
| 2.2 Appraisal Team..... | 2 |
| 2.3 Site Visits..... | 2 |
| 3 Inspection Results | 2 |
| 4 Noteworthy Practices..... | 3 |
| 5 Conclusion..... | 3 |

Appendices

Appendix 1 Technical Occupational Safety and Health Inspection Findings

1 Introduction

EETD's mission is to perform research and conduct analyses that lead to better energy technologies and to reduce adverse energy-related environmental impact. These activities are carried out in 13 buildings (2, 46, 51, 51F, 53, 62, 63, 67, 70, 71, 71T, 90 and 903) which house approximately 65 laboratories and 275 offices.

The Integrated Functional Appraisal (IFA) is a key component of Berkeley Lab's Integrated Safety Management (ISM) system. It is part of Core Function number 5 (Continuous Improvement) of the ISM concept, and forms one of the three tiers of the Laboratory's safety-assessment program that evaluates the ongoing effectiveness of divisions' ISM programs. Berkeley Lab's EH&S Division has been conducting IFAs of all Laboratory organizations since 1996, with each organization undergoing review every three years. EETD's last IFA was conducted during 2001.

2 Appraisal Process

2.1 Determination of Scope, Preparation for Site Visits

An EH&S industrial hygienist was appointed as Team Leader to initiate, plan, and implement the IFA. He consulted with the EETD Safety Coordinator to develop the scope of the IFA walkthrough and selected team members to participate in the review. The scope was based primarily on the EETD FY-2004 Facilities Overview, with an emphasis on areas that had formal authorizations. The Facilities Overview is an internal EETD document that lists EH&S-related information, including activities conducted in EETD spaces, Activity Hazard Documents (AHDs), Radiological Work Authorizations (RWAs), Sealed Source Authorizations (SSAs), as well as Hazards Equipment Authorization Review (HEAR) and Chemical Management System (CMS) data. Other sources of information such as previous Division Self-Assessment reports, IFA reports, and information from the AHD database were considered as well. From this effort, an IFA scope listing the buildings and rooms to evaluate was developed. A representative number of offices and other areas having no formal authorizations were selected by the EETD Safety Coordinator for appraisal as well. It was agreed that the IFA would not duplicate other appraisal and information-gathering systems already in place. Therefore, issues such as Job Hazards Questionnaire (JHQ)/training completion, Supervisors Accident Analysis Reporting System (SAAR) investigation, and Satellite Accumulation Area (SAA) compliance were not evaluated.

2.2 Appraisal Team

The IFA Team Leader assembled an appraisal team consisting of the following individuals. Their respective areas of subject matter expertise are also listed.

Larry McLouth (EH&S) — IFA Team Leader, industrial hygiene, and laboratory safety

Matt Kotowski (EH&S) — General safety, accident prevention, and ergonomics

Kathi Wentworth (EH&S) — Occupational medicine, accident prevention, and ergonomics

Guy Kelley (EETD) — Division Safety Coordinator

Kim Abbott (DOE/BSO) — Observer

2.3 Site Visits

The appraisal team visited the sites on April 19, 21, 26, and May 5, 2004.

At the outset of the initial IFA inspection, the IFA Team Leader briefed the team and the DOE/BSO observer on the purpose, scope, schedule, conduct, and expectations of the IFA. Any EETD room occupants present during the inspection were also informed about the purpose of the IFA.

Forty-two separate rooms distributed throughout seven buildings were visited. Each room inspection consisted of walking through the space, asking staff about the work conducted, and recording observed ES&H issues as well as their corresponding corrective actions. These were logged on data sheets. Findings from each space were discussed with the EETD Safety Coordinator and the person responsible for that space (if present) at the time of the inspection before proceeding to the next space. The EETD Safety Coordinator updated the Division's Hazards, Equipment, Authorizations and Reviews (HEAR) data at the time of the inspections.

3 Inspection Results

Findings and recommended corrective actions resulting from the site visits are presented in Appendix 1. In general, spaces were well maintained. A total of 115 observations were noted during the field inspections. The majority of these were related to electrical safety, chemical safety, and machine guarding. These are summarized below. A detailed list of the IFA findings and recommended corrective actions is presented in Appendix 1.

Formal Authorizations: General observations indicated that EETD's formal authorizations adequately covered the hazards within the Division. However, one AHD (BE1000) had to be updated to include the use of chlorine gas.

Electrical Safety: Electrical safety issues included use of extension cords in lieu of permanent wiring, frayed/damaged electrical cords, lack of bonding and grounding of cable trays, and blocked electrical disconnects and panels. Moreover, several eyewash/safety showers or drench hoses are located near light switches, power outlets, laser interlock panels, and other energized circuits. This was noted during the previous (FY 2001) IFA. This poses a potential shock hazard. A Laboratory-wide effort is underway to correct deficiencies of this nature.

Chemical Safety: In general, chemical safety appeared to be well managed. Some issues were noted though. These included lack of or insufficient secondary containment, clutter in fume hoods, labeling deficiencies.

Machine guarding: Several pieces of equipment (band saws, mills, belt sanders, and drill presses) had exposed (unguarded) moving parts.

4 Noteworthy Practices

EETD addressed a number of safety concerns identified during last IFA (2001). Most notably were seismic safety, housekeeping, and ergonomics, which had all greatly improved. Very few seismic-related deficiencies were noted in the 2004 IFA. Housekeeping had improved dramatically as a result of Division management's involvement. For example, operations were suspended in a problematic wet chemistry laboratory until the area was cleaned. After inspection of the area, operations were allowed to resume but only after the area supervisor developed a plan of action to maintain his area to Division standards. Ergonomics has improved as a result of the Division's focus on evaluating workstations and providing funds to correct deficiencies.

5 Conclusion

Safety within EETD has exceptional management support. The EETD Division Safety Committee is comprised of the Deputy Division Director, Division Business Manager, Division Safety Manager, and the Division Safety Coordinator. It meets on an *ad hoc* basis and focuses on specific EH&S issues. Being comprised of upper-level management, the committee has the authority to allocate funds to correct deficiencies. The safety committee meets with the Division Council on a quarterly basis to keep senior management up to date.

The Safety Coordinator/Safety Manager team effectively administers the safety program, monitors conditions throughout the Division, and identifies issues that need management's attention. They have proven to be a valuable resource by keeping abreast of EH&S issues within the Division and by taking

immediate action on issues before they become problems. EETD's continued success will be assured provided that adequate time and resources are given to the Safety Coordinator/Safety Manager team to carry out their responsibilities.

Appendix 1 Technical Occupational Safety and Health Inspection Findings

| No. | Bldg. | Room | Date | Finding | Corrective Action |
|-----|-------|------|---------|--|---|
| 1 | 46 | 157C | 4/26/04 | Unguarded lamps on lamp test rack | Install guards on bulbs or racks with screen, doors, or similar |
| 2 | 46 | 157C | 4/26/04 | Aisle cluttered | Clean up aisle to remove trip hazards |
| 3 | 46 | 159 | 4/26/04 | Band saw guard inadequate under work table | Improve guard |
| 4 | 53 | 101 | 4/26/04 | Band saw lower guard not adjusted | Adjustment made on the spot |
| 5 | 53 | 101 | 4/26/04 | Bolted down machine tools w/ flexible power cords & plugs | Submit work request to have permanently wired |
| 6 | 53 | 103 | 4/26/04 | N Elect. panel inadequate access due to windows & frames | Clear 30" wide by 36" deep area in front of panel |
| 7 | 53 | 103 | 4/26/04 | W Elect. panel blocked by bicycle | Clear 30" wide by 36" deep area in front of panel |
| 8 | 53 | 103 | 4/26/04 | Considerable Styrofoam stored | Consult with Fire Marshal about fire rating and storage requirements |
| 9 | 53 | 103B | 4/26/04 | Paint spray boot has no sprinkler | Consult with Fire Marshal about sprinkler requirement |
| 10 | 53 | 103B | 4/26/04 | Milar sheet machine without guards for belts, pulleys, gears, etc. | Install guards |
| 11 | 53 | 103B | 4/26/04 | Possible blocked access to blower disconnect switch | Consult with Tom Caronna |
| 12 | 62 | 214B | 5/5/04 | No secondary containment used for liquids (e.g., acetone in fume hood No. 4) | Secondary containment should be large enough to hold 110% of the volume |
| 13 | 62 | 214B | 5/5/04 | Heating mantle has defective cord (strain relief) | Repair or replace cord |
| 14 | 62 | 220 | 5/5/04 | In use 4% H ₂ /He cylinder blocking access to eyewash/safety shower | Relocate cylinder |
| 15 | 62 | 220 | 5/5/04 | Access to eyewash/safety shower partially blocked by glovebox | Submit work request to rotate eyewash 45 deg |
| 16 | 62 | 220 | 5/5/04 | Laboratory personnel have to climb on countertop to access chemicals stored on shelves | Use an 8-foot ladder until adequate storage can be found |
| 17 | 62 | 238 | 5/5/04 | Disconnect is blocked by laser table | Consult with Tom Caronna |

| No. | Bldg. | Room | Date | Finding | Corrective Action |
|-----|-------|------|---------|---|--|
| 18 | 62 | 246B | 5/5/04 | Table obstructs panel | Clear 30" wide by 36" deep area in front of panel |
| 19 | 62 | 246B | 5/5/04 | Combustible materials next to hotplate/stirrer in glovebox | Abated on site |
| 20 | 62 | 246B | 5/5/04 | All gloveboxes except No. 1 has an EH&S inspection sticker on it | Consult with John Seabury |
| 21 | 62 | 246B | 5/5/04 | Glovebox No. 1 - left glove has hole in finger repaired with duct tape | Replace glove |
| 22 | 62 | 246B | 5/5/04 | Lots of clutter and chemicals in glovebox | Review current chemical usage and keep what is needed |
| 23 | 63 | 101 | 5/5/04 | Aisle has 24" clearance. 28" is required. This exists in several areas | Relocate shelves and cabinets |
| 24 | 63 | 101 | 5/5/04 | In-running nip point under table of 1-inch belt sander | Install guard |
| 25 | 63 | 101 | 5/5/04 | Panel on S wall is obstructed on sides | Consult with Tom Caronna |
| 26 | 70 | 103 | 4/19/04 | Work bench has transite sheet with loose fibers protruding from holes | Researcher doesn't need bench. EH&S to provide guidance for disposal |
| 27 | 70 | 103 | 4/19/04 | Clutter in Fume Hood No. 3 | Remove clutter |
| 28 | 70 | 103 | 4/19/04 | Centrifuge has no interlock — Fume Hood No. 2 | Researcher removed from service |
| 29 | 70 | 103 | 4/19/04 | Centrifuge has no interlock — Fume Hood No. 4 | Disconnect from service |
| 30 | 70 | 108C | 4/19/04 | Panel and disconnect are blocked by portable file | Clear 30" wide by 36" deep area in front of panel |
| 31 | 70 | 108C | 4/19/04 | Unapproved cable from Panel PNL-140-70 — Use is unknown, but probably ground wire | Consult with Tom Caronna |
| 32 | 70 | 108C | 4/19/04 | Access/Egress — Unrestrained files stacked along aisle near exit | Relocate the files or consider lateral file cabinet |
| 33 | 70 | 108C | 4/19/04 | Plug in outlet on E wall has exposed wires | Repair or replace |
| 34 | 70 | 108C | 4/19/04 | Cable trays - No evidence of bonding and grounding | Consult with Tom Caronna |
| 35 | 70 | 108C | 4/19/04 | Lead vault not seismically anchored | Submit work request |
| 36 | 70 | 123 | 4/19/04 | Insufficient guarding on Delta mill, band saw, belt sander, & drill press | Install guards — OSHA finding |
| 37 | 70 | 123 | 4/19/04 | Elephant trunk not tested by EH&S | Enter into EH&S testing database |

| No. | Bldg. | Room | Date | Finding | Corrective Action |
|-----|-------|------|---------|--|---|
| 38 | 70 | 123 | 4/19/04 | Seismic anchor for brake was unbolted | Replace bolts with pins to allow moving the brake when needed |
| 39 | 70 | 133 | 4/19/04 | X-ray producing equipment | Have Ted Decastro evaluate use, authorization, & signage |
| 40 | 70 | 133 | 4/19/04 | Microdrill's top is removed, exposing mechanism | Replace top or guard, otherwise discontinue use |
| 41 | 70 | 133 | 4/19/04 | 2 disconnects in NE corner blocked by X-ray equipment | Consult with Tom Caronna |
| 42 | 70 | 133 | 4/19/04 | Signal cable used for 110 V to power warning light at entrance. This is also an open penetration. | Submit work request — rewire or disconnect and close penetration. |
| 43 | 70 | 134 | 4/19/04 | HCl container barcode CH276598 on container but not in CMS | Enter into CMS & confirm that this is an isolated incident |
| 44 | 70 | 134 | 4/19/04 | Flexible gas line penetrates wall; fire safety issue | Submit work request for noncombustible tubing & fire sealing |
| 45 | 70 | 134 | 4/19/04 | Unlabeled volumetric flask & beaker w/ clear liquid, and glass container w/ pink powder | Label contents and primary hazards |
| 46 | 70 | 141 | 4/19/04 | Eyewash/safety shower blocked by 5' steel tubes | Abated on site |
| 47 | 70 | 141 | 4/19/04 | Electrical safety issues: e.g., use of extension cords in place of permanent wiring, bonding, and grounding of cable trays | These will be resolved in the move to 70-173 |
| 48 | 70 | 157 | 4/19/04 | Water line and power cables are in the same cable tray | Consult with Tom Caronna |
| 49 | 70 | 157 | 4/19/04 | Panel blocked in NW wall | Clear 30" wide by 36" deep area in front of panel |
| 50 | 70 | 157 | 4/19/04 | Blocked disconnect on E wall | Clear 30" wide by 36" deep area in front of panel |
| 51 | 70 | 157 | 4/19/04 | No strain relief on digital thermometer cord, E wall | Repair |
| 52 | 70 | 157 | 4/19/04 | Cable trays — no evidence of bonding and grounding | Consult with Tom Caronna |
| 53 | 70 | 163 | 4/19/04 | Container of 2-butoxyethylacetate had no CMS barcode | Ensure all chemicals entered into CMS |
| 54 | 70 | 163 | 4/19/04 | Door between 163 and 157 not interlocked for laser safety. Also large gap in door; laser safety hazard | Consult with Ted Decastro |

| No. | Bldg. | Room | Date | Finding | Corrective Action |
|-----|-------|------|---------|--|---|
| 55 | 70 | 163 | 4/19/04 | Flexible wiring runs from outlet by fume hood to cable tray | Consult with Tom Caronna |
| 56 | 70 | 163 | 4/19/04 | Signal and power cables in same cable tray | Consult with Tom Caronna |
| 57 | 70 | 163 | 4/19/04 | Cable trays; no evidence of bonding and grounding | Consult with Tom Caronna |
| 58 | 70 | 163 | 4/19/04 | Cable running through door between 163 and 157 | Consult with Tom Caronna |
| 59 | 70 | 163 | 4/19/04 | No guard on Accu Cutter paper cutter | Install guard |
| 60 | 70 | 163 | 4/19/04 | Tubing stored in cable trays | Remove tubing |
| 61 | 70 | 163 | 4/19/04 | S door to loading dock not interlocked for laser safety, and no "keep locked" sign | Consult with Ted Decastro |
| 62 | 70 | 163 | 4/19/04 | Calcium gluconate gel 1 mo. Over age | Exchange for new tube at Health Services |
| 63 | 70 | 174 | 4/19/04 | Unused portion of blade on horizontal band saw is exposed | Enclose unused portion |
| 64 | 70 | 174 | 4/19/04 | Guard is loose on the back of band saw | Repair |
| 65 | 70 | 174 | 4/19/04 | Extension cord (in cable tray) used in lieu of permanent wiring | Consult with Tom Caronna |
| 66 | 70 | 174 | 4/19/04 | Cable trays; no evidence of bonding and grounding | Consult with Tom Caronna |
| 67 | 70 | 174 | 4/19/04 | Signal cable penetrating S wall - fire safety issue | Submit work request |
| 68 | 70 | 201 | 4/21/04 | Eyewash/safety shower blocked | Abated on site |
| 69 | 70 | 201 | 4/21/04 | Using extension cord for stirrer | Connect directly to outlet |
| 70 | 70 | 201 | 4/21/04 | Secondary containment too small for large 5 gallon waste can | Secondary containment should be large enough to hold 110% of the volume |
| 71 | 70 | 201 | 4/21/04 | S bench circuit breaker obstructed & unlabeled. In use? | Consult with Tom Caronna |
| 72 | 70 | 215 | 4/21/04 | There is heat tape on the inlet duct near door | Consult with Tom Caronna re: possible need for GFCI |
| 73 | 70 | 215 | 4/21/04 | Lack of secondary containment for chemicals in & under fume hood | Obtain drip tray from stores |
| 74 | 70 | 215 | 4/21/04 | Fume hood inspection out of date | Consult with John Seabury |
| 75 | 70 | 217 | 4/21/04 | 5-gallon cans connected to airline - possible pressure hazard | Must use approved containers rated for pressure |
| 76 | 70 | 217 | 4/21/04 | Housekeeping is poor | Clean area |

| No. | Bldg. | Room | Date | Finding | Corrective Action |
|-----|-------|-------|---------|--|---|
| 77 | 70 | 217 | 4/21/04 | Bottom panel of equipment rack pulled out exposing wires | Close the panel |
| 78 | 70 | 217 | 4/21/04 | 3 - 200 scf cylinders of 0.5 % CO, 356 ppm CO and 500 ppm NO found in room; no authorization to use these gases | Either remove gases or develop an AHD with a hazard analysis for their use |
| 79 | 70 | 217 | 4/21/04 | Exposed ends of bolts protruding from chamber; bump hazard | Put caps on exposed ends |
| 80 | 70 | 218 | 4/21/04 | Panel is too close to the eyewash/safety shower | EH&S will consult with Facilities for corrective action |
| 81 | 70 | 218 | 4/21/04 | Guard on vacuum pump is not large enough | Submit work request |
| 82 | 70 | 223 | 4/21/04 | Panel obstructed by gas lines (N wall) | Reroute gas lines |
| 83 | 70 | 223 | 4/21/04 | 2 wall-mounted pressure receivers; not rated | No longer in use; remove |
| 84 | 70 | 223 | 4/21/04 | Thermal desorption tube conditioner in hood; possible exposed voltage on heating sleeves. Also plugged into power tap along with refrigerator. | Consult with Tom Caronna |
| 85 | 70 | 249 | 4/21/04 | Poor housekeeping | Clean area |
| 86 | 70 | 249 | 4/21/04 | Pressure vessel last tested on 9/17/9 | Confirm this is within testing frequency |
| 87 | 70 | 249 | 4/21/04 | Methane cylinder has a 200 psi second stage | Is this necessary? If not use a second stage for anticipated pressure range |
| 88 | 70 | 249 | 4/21/04 | 5-gallon containers of Sibond (apparently used for aerogel work which has been discontinued) are stored | Dispose of this and other materials in the waste stream if it is no longer used |
| 89 | 70 | 258 | 4/21/04 | There are bare incandescent & fluorescent light bulbs in the clean bench | This needs to have a guard |
| 90 | 70 | 264 | 4/21/04 | Table top centrifuge (GLC 1) has no interlock | Either install an interlock or replace it with a unit that has one |
| 91 | 70 | 264 A | 4/21/04 | Carbon monoxide (40 ppm) and ammonia are stored in this area | If in use or planned for use, review hazards; establish controls, which may include an AHD. Otherwise return to vendor. |
| 92 | 70 | 269 | 4/21/04 | Fume hoods 3,4,5,6, and 7 do not have current EH&S Inspection sticker | Contact John Seabury |

| No. | Bldg. | Room | Date | Finding | Corrective Action |
|-----|-------|-------|---------|--|--|
| 93 | 70 | 269 | 4/21/04 | 500 ppm NO is stored in lab with regulator attached | Remove regulator and put on valve cap |
| 94 | 70 | 269 | 4/21/04 | Centrifuge has no interlock | Either install an interlock or replace unit |
| 95 | 70 | 269A | 4/21/04 | Filing cabinet is not seismically anchored | Submit work request |
| 96 | 70 | 275 | 4/26/04 | Aisle blocked with shipping case, furniture, etc. | Clear aisle |
| 97 | 70 | 275 | 4/26/04 | Housekeeping is poor | Clean area and organize |
| 98 | 70 | 275 | 4/26/04 | Approx. 3-gal compressed air tank without relief valve | Install relief valve. (Press gauge may be lowest press component.) |
| 99 | 70 | 275 | 4/26/04 | Open electrical junction box over door | Contact Work Request to have cover installed |
| 100 | 70 | 278 | 4/21/04 | Housekeeping is poor | Clean area |
| 101 | 70 | 291 | 4/26/04 | Lab user not familiar with laser LOTO procedures. Existence of written laser LOTO procedures not apparent. | Confirm written laser LOTO procedures |
| 102 | 70 | 291 | 4/26/04 | Cable trays; no evidence of bonding and grounding | Consult with Tom Caronna |
| 103 | 70 | 295 | 4/26/04 | Panel blocked on E wall | Clear 30" wide by 36" deep area in front of panel |
| 104 | 70 | 295 | 4/26/04 | Possible inadequate clearance for disconnect switch on E wall | Consult with Tom Caronna |
| 105 | 70 | 295 | 4/26/04 | Leaking electrode & salt deposits on counter | Clean area |
| 106 | 71T | 101 | 4/26/04 | Unistrut racks in aisle way | Clear aisle of trip hazards and potential blockage during earthquake |
| 107 | 90 | 3145A | 5/5/04 | Partitions along aisle way is not anchored | Submit work request |
| 108 | 90 | 3145D | 5/5/04 | Three-shelf bookcase not anchored | Submit work request |
| 109 | 90 | 3145F | 5/5/04 | Heater plugged into power strip | Plug into a wall outlet |
| 110 | 90 | 3145J | 5/5/04 | Four-legged chairs in use | Replace with five-legged chairs (recommendation) |
| 111 | 90 | 3147 | 5/5/04 | Aisle has 24" clearance. 28" is required. | Relocate table |
| 112 | 90 | 3147 | 5/5/04 | Four-legged chairs in use | Replace with five-legged chairs (recommendation) |
| 113 | 90 | 3147B | 5/5/04 | Refrigerator plugged into power strip | Plug into a wall outlet |

| No. | Bldg. | Room | Date | Finding | Corrective Action |
|-----|-------|-------|--------|--|---------------------|
| 114 | 90 | 3147B | 5/5/04 | Black bookshelf and 3 filing cabinets are not anchored | Submit work request |
| 115 | 90 | 3147B | 5/5/04 | Electrical cord running through doorway from 3147 | Remove |